

S1C88650 Manual errata

ITEM transfer rates						
Object manuals	Document code				Object pages	
S1C88650 technical manual	-				63,94	
(Error)						
Table 5.8.4.2, Table 5.10.7.1						
Transfer rate (bps)	OSC3 oscillation frequency / Programmable timer settings					
	f_{OSC3} = 2.4756 MHz	RDR1X	f _{OSC3} = 3.0720 MHz	RDR1X	f _{OSC3} = 3.6864 MHz	RDR1X
19,200	00H	03H	00H	04H	00H	05H
9,600	00H	07H	00H	09H	00H	0BH
4,800	00H	0FH	00H	13H	00H	17H
2,400	00H	1FH	00H	27H	00H	2FH
1,200	00H	3FH	00H	4FH	00H	5FH
600	00H	7FH	00H	9FH	00H	BFH
300	02H	1FH	03H	09H	01H	BFH
150	02H	3FH	03H	13H	02H	5FH
(Correct)						
Table 5.8.4.2, Table 5.10.7.1						
Transfer rate (bps)	OSC3 oscillation frequency / Programmable timer settings					
	f _{OSC3} = 2.4576 MHz	RDR1X	f _{OSC3} = 3.0720 MHz	RDR1X	f _{OSC3} = 3.6864 MHz	RDR1X
19,200	00H	03H	00H	04H	00H	05H
9,600	00H	07H	00H	09H	00H	0BH
4,800	00H	0FH	00H	13H	00H	17H
2,400	00H	1FH	00H	27H	00H	2FH
1,200	00H	3FH	00H	4FH	00H	5FH
600	00H	7FH	00H	9FH	00H	BFH
300	02H	1FH	03H	09H	01H	BFH
150	02H	3FH	03H	13H	02H	5FH

S1C88650 Manual errata

ITEM Interrupt function and input comparison register		
Object manuals	Document code	Object pages
S1C88650 technical manual	404824700	46
(Additional comment)		
Notes: • Set the “chattering-eliminate check time” to “None” before SLP instruction, or else the interrupt by input ports cannot be generated.		